

MG5 Trophy UK upgrading naviextra maps issue


I have been an owner of the MG5 SR Exclusive and could update the nav with no issues.

However, the MG5 Trophy update procedure is not working.


It appears as if the USB is not recognised by the Naviextras Toolbox App

Below is the process I have followed


Start with as instructed an 8GB fat32 USB stick formatted




Then go out to the MG5 Trophy car and go to the settings menu.




Select System



From the system menu I select resource update





Which then brings up the instruction menu ... which gives no guidance about the Naviextras app.



Then start Naviextras app.

Then says connecting and defaults to.



My conclusion is that the update procedure for the Trophy is different from the original exclusive.

Please can you explain why?

